





SICUREZZE PER GANCI e TERMINALI A PRESSARE PER FUNI

SIC	CODICE	MISURA (mm)		PORTATA GANCIO (t)	
		B	N	Alta Resistenza	UNI ad occhio
	201	32	7,9	0,80	-
	202	36	7,9	1,00	0,25
	203	40	6,0	1,60	0,50
	204	45	6,0	2,00	0,63
	205	49	7,0	-	0,80
	206	53	8,0	3,20	-
	207	60	11,1	-	1,00
	208	70	11,1	5,00	1,60
	209	75	11,1	-	2,00
	211	71	16,7	-	-
	212	81	16,7	7,50	2,50
	213	90	16,7	10,00	3,20-4,00
	215	134	24,0	15,00-20,00	10,00

	301	34	7,4	0,80	-
	302	35	7,4	1,00	-
	303	39	11,1	1,60	-
	304	41	11,1	2,00	-
	305	50	11,1	3,20	-
	306	68	16,2	5,00	-
	307	75	17,7	7,50	-
	308	84	23,0	10,00	-
	309	115	23,0	15,00	-

TF	CODICE	Ø FUNE (mm)		DIMENSIONI (mm)		MARK
		min.	max.	ø	o	
	06	5,8	6,7	17,5	17,5	1 / 4
	07	6,8	8,3	20,6	20,6	5 / 16
	10	8,4	10,0	20,6	20,6	3 / 8
	11	10,1	11,7	25,4	25,4	7 / 16
	12	11,8	13,3	25,4	25,4	1 / 2
	14	13,4	15,0	30,2	31,8	9 / 16
	16	15,1	16,7	30,2	31,8	5 / 8
	18	16,8	19,8	35,1	38,1	3 / 4

TE	CODICE	Ø FUNE (mm)		DIMENSIONI (mm)		MARK
		min.	max.	c	d	
	06	5,8	6,7	38,1	19,1	1 / 4
	07	6,8	8,3	42,9	22,2	5 / 16
	10	8,4	10,0	42,9	22,2	3 / 8
	11	10,1	11,7	50,8	27,0	7 / 16
	12	11,8	13,3	50,8	27,0	1 / 2
	14	13,4	15,0	63,5	31,8	9 / 16
	16	15,1	16,7	63,5	31,8	5 / 8
	18	16,8	19,8	76,2	36,5	3 / 4

altre misure a richiesta